

This document describes the features, operational issues, and major fixes for the new Sarix Value Series cameras. Review each section to determine if an upgrade is warranted for your installation. For additional information on the camera (including the latest updates to documentation, product specifications, and software downloads), visit the Pelco Web site at www.pelco.com.

Note: For technical issues, contact Pelco Product Support at 1-800-289-9100 (USA and Canada) or +1-559-292-1981 (international).

01.0.0.2a10 Release

Major Fixes

- Corrected an issue with SetUser request failing to create new user if the username is not 'root'.
- Corrected a problem with Audio Detection alarms not triggering Events (e.g. upload to FTP, send email).
- Corrected an issue with running ONVIF API createusers not creating the root user.
- Corrected a problem with the Web Client being slow with pages often taking several seconds to load.
- Corrected issues to improve cybersecurity.
- Corrected a problem with audio being enabled by default.
- Corrected an issue with Milestone and the ONVIF Driver causing the 5MP camera to not stream live video.



Pelco, Inc.
625 W. Alluvial, Fresno, California 93711 United States
(800) 289-9100 Tel
(800) 289-9150 Fax
(missing or bad snippet)
(missing or bad snippet)
www.pelco.com

Pelco, the Pelco logo, and other trademarks associated with Pelco products referred to in this publication are trademarks of Pelco, Inc. or its affiliates. ONVIF and the ONVIF logo are trademarks of ONVIF Inc. All other product names and services are the property of their respective companies. Product specifications and availability are subject to change without notice.

© Copyright 2020, Pelco, Inc. All rights reserved.